

SYNTEKO NATURAL

1608



Synteko NATURAL is an alkyd based solvent-free, faintly smelling oil with excellent properties. The oil is formulated for treatment of wood floors but also cork floors, wooden stairs, windowsills, benches etc.

AREA OF USE:

especially recommended in areas where a high wear resistance is needed

PRODUCT PROPERTIES:

- no solvent
- practically odour-less
- very good good coverage
- short drying time
- easy to use
- non-yellowing
- excellent resistance to wear
- can be tinted with Synteko Tinting Paste

COVERAGE:

- 15 – 60 m²/l, depending on tools and wood species

TOOLS:

- Steel or rubber spatula. 300-500 mm width
- Red pad
- Cloth or trowel for polishing
- Clean tools with white spirit (UK). Place used pads, cloths, spillages and waste in a sealed, water filled metal container immediately.

TECHNICAL DATA:

Base material	Alkyd ester
Solvents	No solvent
Viscosity	320 cP ICI at 23 °C (73°F)
Density	Approx. 955 kg/m ³ (8,64 lbs./gal US) (10,37 lb/gal UK)
Fire hazards	Not flammable
Time for application	It is recommended to wait about 3 hours after the last application before the final buffing is made
Drying time	Approx. 16 hours at 23°C (73°F)/50% RH
Storage	Store frost-free. Must be stored between +10°C (+50°F) and +30°C (+86°F)
Self life	24 months in unopened container from production date (s. package)
Package size	1L, 5L

BEFORE USING THE FLOOR

- The floor can be used 1-2 days after the last polishing
- Do not wet a floor treated with Synteko floor oils during the first week
- Wait for 3 days before laying rugs or carpets
- Do not use vapour-proof, non-skid underlays or other coverings
- Attach felt pads to the legs of chairs and tables in order to avoid scratching the finish.
- Vacuum or dry-mop floors regularly

ATTENTION!

- Do not allow unabsorbed oil to dry! Dried unabsorbed oil produces glossy spots on the surface.
- Too much oil will result in a longer drying time and longer time for over-coating.
- On wood with low absorption, leave some areas untreated during the first application. These areas will be filled during the redistribution procedure.
- The oxygen curing process will be extremely slow if the temperature is below 18 °C.
- Do not polish the surface while warm so as to avoid bleeding back of the oil.
- Be sure to start regular maintenance before the surface is worn through to bare wood.
- **NB!** Place all organic materials like cloth in a metal container filled with water for at least 16 hours to avoid self-combustion. Dispose of them according to regulations.



SYNTEKO NATURAL DIRECTIONS FOR USE



PREPARATION OF UNFINISHED FLOORS OR FLOORS WHERE OLD FINISH MUST BE REMOVED

SANDING

Sand floors using accepted MFMA, NWFA or NOFMA procedures (US). Machine sand the surface to remove old treatments and impurities in the wood. Sand the floor to bare wood - free from old finish, dirt and unevenness. The first sanding is done with a coarse sandpaper and high roller pressure. Make the floor surface as even as possible. If the floor is uneven in spots, sand locally to even out these areas.

The final sanding is done with 100-120 grit sandpaper or screen, and with the lowest possible roller pressure.

Important! Vacuum and tack the floor before applying Synteko Natural Oil. Do not forget to remove dust on skirtings, windowsills, radiators, etc.

TINTING

The mixing of Natural Oil with Tinting Paste 1675 is easily done by adding the tinting paste to the sealer and shaking the container thoroughly. Always use full tubes of tinting paste. Be sure to completely empty the tube into the oil in order to avoid colour differences

DURING THE USE:

- The oil should have room temperature.
- Floor temperature must be between 15 and 25°C (60 to 77°F)
- Floor moisture content must be between 5 and 15%
- The moisture content of the wood should be between 5% and 12%.
- Shake the can carefully before and during use.
- Do not apply areas larger than 25 m² at a time (10 m² at a time in good drying conditions).

APPLICATION AND POLISHING

Before starting work, protect adjacent areas against splashing and spilling. The number of coats necessary depends on how much oil the floor will absorb. The best result is obtained with several thinner coats. Softwoods and beech absorb more; hard and exotic (oily) woods absorb less oil. The wood should be well fed, but not overfed.

Plan your work well, large areas should be divided into smaller areas of 15 - 50 m² (800-3200 sq.ft/ gallon) or areas which are possible to handle in 20 minutes. In hot, dry weather the areas should be further reduced. Shake the can carefully before and during the use.

Apply Synteko Natural Oil with an applicator with rubber blade (squeegee), with a steel spatula or pour directly on floor and distribute with red pad. Use a small brush or a small applicator in areas where it is difficult to reach with the normal applicator. Too much sealer in puddles will splash around. Use 150 r.p.m. or similar adjustment of the buffer.

Redistribute the sealer with a red pad - it is necessary to start within 20 minutes in normal temperatures. Add more oil if necessary. Repeat the process as long as the wood is absorbing the oil. When the wood is saturated, rub the whole surface with a red pad using a 150 r.p.m. buffer. Remove all excess sealer with a cloth and a red pad. Change pad when it is filled up.

After 3-16 hours the floor must be buffed using a red pad. Final polishing is done with a dry non-flocculent cloth wrapped around the pad and 150-300 r.p.m. adjustment of the buffer.

Note: Do not allow unabsorbed oil to dry! Dried unabsorbed oil gives glossy spots on the surface. Re-polish secondary bleeding of oil with red pad before exposure to traffic 1 to 2 days after final polishing. Wait for 3 days before placing rugs or carpets and do not use vapour proof, non-skid underlayments or other coverings.



SYNTEKO FLOOR OILS CARE AND MAINTENANCE



Surfaces treated with Synteko floor oils are easy to keep clean. Regular maintenance will restore your floor's lustre and keep it looking beautiful for very long time.

Vacuum cleaning and, if necessary, mopping with a **Synteko Soap 1617** solution and a well wrung cloth is normally sufficient. Marks from rubber heels, shoe polish, lipstick, ink, etc. should be removed immediately with **Synteko Remover 1692** or with mineral spirits. Avoid scrubbing with coarse brush or strong detergents.

For periodic maintenance of floors treated with Synteko oils use **Synteko Re-Cover 1620**. How often you use it will depend on the amount of traffic and how often the floor is cleaned:

- normally every other year for residential areas
- approx. 2–4 times per year for commercial areas.

Be sure to begin regular maintenance before you wear through to the bare wood. You can also use Re-Cover for local repairing.

How do I use Soap 1617?

When necessary, for regular cleaning, but no sooner than one week after oil treatment. Floors may be washed with a 1:20 dilution of Synteko Soap in lukewarm water, using a well wrung cloth.

How do I use Remover 1692?

Vacuum or mop the floor to remove any dirt. Prepare Synteko Remover as follows:

- For normal cleaning, ½ - 1 part Synteko Remover to 100 parts water
- For heavy cleaning, 2–3 parts Synteko Remover to 100 parts water

Soak a cloth in the mixture; do not pour it directly onto the floor. Wet mop, let the mixture act for a few minutes and then dry mop. Further cleaning with 1 part vinegar to 9 parts water is recommended if sanding and recoating is to be done. The floor must be completely dry before screening and recoating.

How do I use Re-Cover 1620?

Clean the floor with a Synteko Remover solution. Make sure the floor is completely dry before applying Synteko Re-Cover. Apply it thinly with a rubber spatula, floor cloth or similar. Allow the floor to absorb the Re-Cover for 10–15 minutes before applying it again (if necessary). Let the surface dry for 20 minutes and polish the floor with a clean, dry, non-flocculent floor cloth. The floor may be used after 2–4 hours.

Read also separate product information for Re-Cover 1620.

HEALTH & SAFETY INFORMATION

Safety data sheet available for professional user on request. Detailed information and guidance is provided in our MSDS (Material Safety Data Sheet) www.synteko.com. The following only represents a selection of important information.

RISK OF SELFIGNITION! CONTAINS DRYING OIL. COLLECT AND KEEP SPILLAGES, USED RAGS ETC IN FIREPROOF CONTAINER AND DESTROY.

Note: Keep out of reach of children. If swallowed, seek medical advice immediately and show this container or label.

Contains: Co-salt. May produce an allergic reaction.

Our information is based on laboratory tests and is considered a guide in connection with choice of product and working method. As your working conditions are beyond our control, we do not assume any responsibility for the results. Our responsibility covers exclusively personal injury and damage to property, which actually have been proved subsequent to faults and defects in one of the products manufactured by us.



Producer:
Akzo Nobel, Estonia
www.synteko.com

Date: 26.02..2010

